

HDHY Engineering, Inc.

Michael D. Hanson, P.E.
W. Patrick Dunn, P.E.
Brian J. Hefferman, P.E.
Joseph A. Yoder, P.E.

May 25, 2007

Farmers Alliance Insurance
1122 N. Main
McPherson, Kansas 67460

Attention: Mr. Terry Krier
Subject: Professional Engineering Assessment of a Structure.
Insured: Robert and Ruth Wedel
Your File: Policy # 1 15 AR 096132
HDHY File: 07031


Dear Mr. Krier:

At your request, I examined the Robert and Ruth Wedel residence located at 510 W. Scott Street in Greensburg, Kansas following a tornado. A full report on this matter is being prepared and will be sent to you with photographs documenting observations when it is finished.

The structure of the house was found to be in generally good condition. The house was not moved from its foundation. It was not racked or twisted from the winds associated with the tornado. The house can be returned to its pre-tornado condition.

The roof covering and a few pieces of roof sheathing were removed during the tornado and should be replaced as soon as possible to prevent further damage to the interior of the house. Measures should be taken immediately to dry the interior finishes and insulation to prevent mold growth.

HDHY Engineering, Inc.



Joseph A. Yoder, P.E.
Consulting Engineer