

**LIQUID WASTE HAULER LOAD TICKET**

**NOTICE: Wastes brought to the Las Vegas Street Facility are limited to domestic wastes and kitchen/food service grease traps. Commercial, industrial or hazardous wastes are prohibited.**

HAULER COMPANY NAME Tri-County Septic Service

TRUCK LICENSE # 667 XFL PERMIT # 22-LW4070

DATE PUMPED: 6/16/22 TIME PUMPED: 11:45 am/pm

DATE DUMPED: \_\_\_\_\_ TIME DUMPED: \_\_\_\_\_ am/pm

CUSTOMER NAME Petar Kavacovich

AUTHORIZED REPRESENTATIVE OF CUSTOMER owner

CUSTOMER ADDRESS 39466 Hwy 24, Lake George, Co 80827

CUSTOMER PHONE NUMBER: 409-795-0589 BUSINESS  or RESIDENCE

**TYPE OF VESSEL PUMPED:**  
 SEPTIC TANK  GREASE TRAP  OTHER (DESCRIBE) \_\_\_\_\_

APPROXIMATE GALLONS PUMPED: 1000 gallons

**DISPOSAL LOCATION:**

Colorado Springs Utilities  
 Septic Disposal Station  
 737 E Las Vegas St. Gate # 19  
 Colorado Springs, CO 80903

Reliable Sanitation  
 2239 Commercial Blvd.  
 Colorado Springs, CO 80906

Other: \_\_\_\_\_

Address: \_\_\_\_\_

**LIQUID WASTE HAULER CERTIFICATION:**

I certify under penalty of the law that the above information is true and correct to the best of my knowledge. Furthermore, I certify that the truck listed above contains the materials listed above in Customer's Certification, and does not contain hazardous waste as defined by the Resource Conservation and Recovery Act.

[Signature] 6/16/22  
 HAULER SIGNATURE DATE

Robert G. Johnson owner  
 PRINT NAME/TITLE

**Recommended Grease Trap/Interceptor Observations: (check all that apply)**

- Trap/Interceptor left empty following pumping.
- Manhole lid(s) accessible.
- "T" present on outlet side of tank.
- Cap present on outlet "T".
- Interceptor baffle present & in good condition.

**WARNING: Falsification or omission of the information required above is grounds for immediate permit revocation and suspension of dumping privileges.**

This form is intended for internal waste tracking and verification by Colorado Springs Utilities and is not an endorsement of the activities of the waste hauler.



# Park County Environmental Health Department

856 Castello Ave • P.O. Box 517, Fairplay, CO 80440

Office: 719-836-4267

EHS@PARKCO.US

## On-Site Wastewater Treatment System

### Transfer of Title Inspection Report

#### 1. Inspector Information

Company Name: Tri-County Septic Service, Inc

Company Mailing Address: P.O. Box 428, Florissant, Co 80816

Inspector: Pat Lohmeier Phone: 719-748-1440

Email: patlohm@yahoo.com NAWT Cert. # Required: 129391TC

#### 2. System Information

Property Address: 39466 Hwy 24, Lake George, Co 80827

Age of OWTS: \_\_\_\_\_  Water softener  Garbage disposal  Whirlpool

In-home business?  Yes  No Type: \_\_\_\_\_

Number of people currently occupying dwelling: 0

If currently unoccupied, for how long has it been vacant? Vacation

Number of bedrooms in dwelling: 2

Has there ever been a backup in the house?  Yes  No

List known repairs made to the system: NONE

Date septic tank was last pumped: 6/26/22  Never to my knowledge

At what frequency? \_\_\_\_\_ Company: Tri-County Septic Service

#### 3. Property Owner Information

Name: Peter Kovacevich Phone: 409-795-0585 Email: pkovaca@aol.com

The above information is true to the best of my knowledge

Owner Signature: [Signature] Date: 6/16/22  
Agent



## Park County Environmental Health Department

856 Castello Ave • P.O. Box 517, Fairplay, CO 80440

Office: 719-836-4267

[EHS@PARKCO.US](mailto:EHS@PARKCO.US)

Site	Acceptable	Unacceptable	N/A
Erosion-properly graded, not eroded or gullied	✓		
Improper Discharges- no secondary surface wastewater points such as gray water lines, washing machine lines, etc.	✓		
Proper vegetation – area of system is free of trees and/or shrubs	✓		
Safe from compaction- components are not located in an area subject to compaction ie; under a structure or corral	✓		
<b>Tank</b>			
Correct slope entering the tank	✓		
Internal baffles/tees present, solid, and in good condition	✓		
Effluent is at appropriate level	✓		
Internal condition – no corrosion, erosion, root infiltration: tank is water tight	✓		
Tank access at grade or above	✓		
Risers in good condition	✓		
Access lids are durable, weather-resistant and in good condition	✓		
Filtration component present – Doser/Pump/Filter - filter must be accessible and good condition	✓		
<b>Pump Tank, Ejector or Grinder Pump</b>			✓
Pump elevated off the bottom of the chamber		/	
Doser/pump operates properly			
If there is a check valve, purge hole is present			
High water alarm operates properly			
<b>Soil Treatment Area</b>			
Probe to determine location, excessive moisture, odor, and/or effluent	✓		
No indication of a previous failure	✓		
No seepage visible on surface	✓		
No indication of effluent surfacing (i.e., no unusually lush vegetation present)	✓		
No ponding water in the distribution media	✓		
Even distribution of effluent in the field	✓		



**Park County Environmental Health Department**

856 Castello Ave • P.O. Box 517, Fairplay, CO 80440

Office: 719-836-4267

EHS@PARKCO.US

**Tank Information:**

Type:  Concrete    Poly/Plastic    Metal (unacceptable)    Other

Number of compartments: 2   Tank size: \_\_\_\_\_

Mid seam tank:  No    Yes (water tightness test required)

Secondary Tank:  Yes    No

Type:  Concrete    Poly/Plastic    Metal (unacceptable)    Other

Pump records attached (required)

Risers Added: Yes   No   Existing   Screen Added: Yes   No   Existing

Does the system contain a dosing or pump tank, ejector or grinder pump?

Yes   No

Aeration, Mechanical or Higher-Level Treatment Additions? Yes   No

Is there an active O&M Agreement Yes   No   Date of last inspection? \_\_\_\_\_

**Soil Treatment Area**

Approximate distance between water well and STA: 200+

**Explain answers as necessary and additional information:**



# Park County Environmental Health Department

856 Castello Ave • P.O. Box 517, Fairplay, CO 80440

Office: 719-836-4267

[EHS@PARKCO.US](mailto:EHS@PARKCO.US)

Please attach the pump receipt & sketch of system (include relation to physical features)

