

STATE OF TEXAS WELL REPORT for Tracking #568929

Owner: Ernesto Mendoza	Owner Well #: 1
Address: 4287 PR 1391 Gatesville, TX 76528	Grid #: 40-33-7
Well Location: 4287 PR 1391 Gatesville, TX 76528	Latitude: 31° 23' 01" N
Well County: Coryell	Longitude: 097° 59' 32" W
	Elevation: 1095 ft. above sea level

Type of Work: New Well	Proposed Use: Domestic
-------------------------------	-------------------------------

Drilling Start Date: **3/16/2021** Drilling End Date: **3/17/2021**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	8.75	0	30
	6.75	30	610

Drilling Method: **Air Rotary**

Borehole Completion: **Straight Wall**

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	0	30	Cement 5 Bags/Sacks

Seal Method: **Hand Mixed**

Sealed By: **Driller**

Distance to Property Line (ft.): **No Data**

Distance to Septic Field or other concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: Surface Sleeve Installed	Surface Completion by Driller
---	--------------------------------------

Water Level: **No Data**

Packers: **Rubber at 30 ft.
Rubber at 40 ft.
Rubber at 42 ft.
Rubber at 500 ft.
Rubber at 502 ft.**

Type of Pump: **No Data**

Well Tests: **Jetted** **Yield: 1 GPM after 1 hours, no drawdown specified**

Water Quality: **Strata Depth (ft.)** **No Data** **Water Type** **No Data**

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Lucy Creek Water Well Service**
PO Box 1847
Lampasas, TX 76550

Driller Name: **Juan Munoz** License Number: **54176**

Apprentice Name: **Mario Munoz** Apprentice Number: **60427**

Comments: **TDS: 1260 PPM**

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL			Casing: BLANK PIPE & WELL SCREEN DATA					
Top (ft.)	Bottom (ft.)	Description	Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
0	1	Topsoil	4.5	Blank	New Plastic (PVC)	SDR-17	0	37
1	7	Tan L.S.	4.5	Perforated or Slotted	New Plastic (PVC)	SDR-17 0.125	37	40
7	15	White L.S.	4.5	Blank	New Plastic (PVC)	SDR-17	40	550
15	25	Tan L.S.	4.5	Perforated or Slotted	New Plastic (PVC)	SDR-17 0.125	550	610
25	27	Grey L.S.						
27	37	Grey Shale						
37	40	Paluxy Tan Sand						
40	360	Grey L.S. + Shale Clay						
360	380	Tan L.S.						
380	475	Red Clay w/ Pale White L.S.						
475	563	Red Clay w/Green/Brown Shale						
563	590	Brown L.S. + Grey Black Shale L.S. Shale						
590	610	Black Shale						

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540